



NORDAM TR5000 Series Service & Repair



TR5000 Series Service & Repair

Nordam Thrust Reverser's are notorious for corroding. Door inner deflector skins, blister areas and pivot fittings corrode as a factor of use, so when it happens to you, remember **AVMATS Jet Support**. Our repair program will replace damaged skins and pivot fittings and repair corroded blister areas and get you back in the air fast. In many cases we can offer loaner or exchange units to get you back up even quicker!

AVMATS Jet Support offers complete Thrust Reverser service and repair. After replacement of defective parts, a full functional check will be accomplished to the entire Thrust Reverser assembly. The check verifies repairs, checks latch/unlatch switches and hydraulic actuators. We currently offer service for the following models:

TR5000
(Hawker 800A)

TR5000BR
(Hawker 750XP, 800XP & 850XP)

TR5020
(Falcon 20-5)

TR5050
(Hawker 900XP)